



SPECIAL NOTE:

Some valve covers do not have baffled oil fill holes due to clearance problems when used with certain high performance valve train components. If your application requires baffles because of excessive valve train oil splash, we recommend using Mr. Gasket Baffled Breather Grommets (P/N 5425) available at your local Mr. Gasket retailer or www.holley.com.

97140006

Date: 5-23-17



SPECIAL NOTE:

Some valve covers do not have baffled oil fill holes due to clearance problems when used with certain high performance valve train components. If your application requires baffles because of excessive valve train oil splash, we recommend using Mr. Gasket Baffled Breather Grommets (P/N 5425) available at your local Mr. Gasket retailer or www.holley.com.

97140006

Date: 5-23-17



SPECIAL NOTE:

Some valve covers do not have baffled oil fill holes due to clearance problems when used with certain high performance valve train components. If your application requires baffles because of excessive valve train oil splash, we recommend using Mr. Gasket Baffled Breather Grommets (P/N 5425) available at your local Mr. Gasket retailer or www.holley.com.

97140006

Date: 5-23-17



SPECIAL NOTE:

Some valve covers do not have baffled oil fill holes due to clearance problems when used with certain high performance valve train components. If your application requires baffles because of excessive valve train oil splash, we recommend using Mr. Gasket Baffled Breather Grommets (P/N 5425) available at your local Mr. Gasket retailer or www.holley.com.

97140006

Date: 5-23-17